

154260

Recording Requested By
and
When Recorded Mail To:
City of Riverside
3900 Main Street
Riverside, CA 92522
Attn: City Engineer

RECEIVED FOR RECORD
Min. Past 5 o'clock

MAY 12 1989
Recorded in Official Records
of Riverside County, California
William E. Williams
RECORDED

CERTIFICATE OF CORRECTION

NAME: HUGH E. HALDERMAN certifies
(Registered Civil Engineer)

That I am a _____ of the State of California:

That (Parcel) Map No. 22857 was prepared by _____
Name
Hugh E. Halderman RCE 8793

Registration/License No. _____
and is filed in Book 150, Pages 41-42 of (Parcel) Maps,
Records of Riverside County, California, and that the following corrections
to said map are made by me in accordance with Chapter 3, Article 7, Section
66469 thru Section 65472 of the Subdivision Map Act.

That the following data shown on said (Parcel) Map (is incorrect) and is
corrected as follows:

Correct the character of the following monuments:

1. The southeasterly corner of Parcel 4 set a lead, tack, and tag stamped RCE 8793 in concrete gutter.
2. The northwesterly corners of Parcel 1 set a concrete nail and tag stamped RCE 8793 in footing.
3. The southwesterly corner of Parcel 6 set a lead, tack, and tag stamped RCE 8793 on walk.
4. The southwesterly corner of Parcel 7 set a concrete nail and tag stamped RCE 8793 in top of wall.
5. The northeasterly corner of Parcel 4 set a concrete nail and tag stamped RCE 8793 in top of wall.
6. The northeasterly corner of Parcel 5 set concrete nail and tag stamped RCE 8793 in wall footing.

The following monuments were offset due to physical obstruction of the point by existing improvements:

1. The northwesterly corner of Parcel 9 set a spike and washer stamped RCE 8793 in A.C., South 34° 22' 45" East 5.00 feet and North 55° 37' 15" East 5.00 feet from the true corner.
2. The southwesterly corner of Parcel 9 set 1" I.P. stamped RCE 8793 in landscaped planter, South 55° 37' 15" West 2.00 feet from the true corner.
3. The southeasterly corner of Parcel 7 set lead, tack and tag stamped RCE 8793 in concrete gutter, North 55° 37' 15" East 5.00 feet from the true corner.
4. The southwesterly corner of Parcel 10, set spike and washer stamped RCE 8793 in A.C., South 34° 22' 45" East 2.00 feet from the true corner.
5. The northwesterly corner of Parcel 11, set 1" I.P. stamped RCE 8793 in landscaped planter, South 34° 22' 45" East 2.00 feet and North 55° 37' 15" East 2.00 feet from the true corner.

See also attached Exhibit A.

There are no fee property owners affected by this correction


Dated: February 16, 1989 Hugh E. Halderman
(Registered Civil Engineer, No. 8793)

State of California : ss.
County of Riverside

On February 16, 1989, before me, the undersigned, a Notary Public in
and for said County and State, personally appeared Hugh E. Halderman
known to me to be the person whose name is subscribed to the
within instrument and acknowledged that he executed the same.

WITNESS my hand and official seal.

Seal
My Commission Expires January 1, 1991 Signature Joyce E. Williams
Notary Public



CITY ENGINEER'S CERTIFICATE

This certificate of correction has been examined by the undersigned and
such examination disclosed that the only change(s) shown are in conformance
with Section 66469(a) thru (e) of the Subdivision Map Act and Title 18
(Subdivision Ordinance) of the City of Riverside Municipal Code.

Dated: May 9, 1989
BARRY BECK
Riverside City Engineer
By Barry Beck

MAP HAS BEEN MARKED WITH
CERTIFICATE OF CORRECTION
RECORDING DATA.
Please record for the benefit of the City of
Riverside
Property Services Manager

